



# DIAMONDBACK™

F I R E A R M S

TO: All Diamondback Firearms Distributors  
FROM: Evin Galbraith, National Sales Manager  
DATE: August 2, 2012  
RE: DB9 Laser Warranty Issue

Recently we uncovered an issue with our DB9 series of pistols capable of accepting the Crimson Trace Laser. The LG-491 model supplied by CTC, when mounted on our DB9 Series pistols, was not compatible, causing our pistols to experience cyclical failures by placing pressure on the frame and restricting its ability to “flex” during its range of motion. This LG-491 by CTC fits only the DB380, not the DB9mm and it states so in all literature and packaging.

To date, Diamondback Firearms, LLC has not shipped any of the DB9CTC models with the laser installed to any distributor. However, we have discovered that some were shipped WITHOUT the CTC laser and the End-Users may have installed this product, or a similar laser/light type product on their own.

This situation causes undue stresses to be placed on the frame which may result in cyclical failures or permanent damage to the pistol. **DB cannot warranty such circumstances as created by these added products** and we advise that your dealers who may have purchased the laser-compatible 9mm models be notified this situation will void the warranty.

Any issues with the CTC product specifically, should be referred to Crimson Trace Corporation.

If you have any questions, please contact me directly.

Thank you very much for your continuing efforts at promoting Diamondback Firearms!

Most Respectfully,

Evin Galbraith  
National Sales Manager  
Diamondback Firearms, LLC  
Direct Line: 321.474.8874  
[e.galbraith@diamondbackfirearms.com](mailto:e.galbraith@diamondbackfirearms.com)